

IIL No.	Part No.	Description	Qty. Rqd.
---------	----------	-------------	-----------


INSTRUMENTS AND SWITCHES

REMARKS LEGEND -


Vehicle i.d. (v) numbers:

- JA = 1988 model year; KA = 1989 model year;
- LA = 1990 model year; MA = 1991 model year;
- NA = 1992 model year; PA = 1993 model year;
- RA = 1994 model year; SA = 1995 model year.



MONEY-SAVING KITS NOTED IN RED TYPE



1	PRC4348	SPEEDOMETER, MPH Up to (v) KA399972	1
	RTC6599G	SPEEDOMETER, MPH From (v) LA399973 to RA647649	1
	STC1312G	SPEEDOMETER, MPH From (v) SA647650 on	1
2	PRC43520E	ANGLE DRIVE, speedometer Up to (v) KA399972	1
3	ADU6262LG	BULB AND HOLDER, instruments Up to (v) JA351032	19
4	RTC6607G	BULB HOLDER, instruments, 1.12W, black body From (v) LA399973 on	A/R
	RTC6580G	BULB HOLDER, instruments, 2W, blue base From (v) LA399973 to RA647649	1
5	RTC6608G	BULB HOLDER, instruments, 1.12W, long From (v) LA399973 to RA647649	1
6	PRC6278	CABLE, speedometer, upper Up to (v) NA models	1
7	PRC7949	CABLE, speedometer, lower Up to (v) NA models	1
	PRC7949	CABLE, speedometer, lower From (v) LA399973 on	1
8	NTC6115G	HEAT SHIELD, speedometer cable	1



IIL No.	Part No.	Description	Qty. Rqd.
---------	----------	-------------	-----------




9	503352	BULB, clock	1
10	PRC9410	CIGAR LIGHTER ASSEMBLY Up to (v) RA647649	1
11	RTC3635	BULB, cigar lighter	1
12	PRC5712G	LOCK ASSY, steering, with ignition switch Non-interlock; up to (v) NA models	1
	NTC9440	LOCK ASSY, steering, with ignition switch With interlock; up to (v) NA models	1
	NTC9588G	LOCK ASSY, steering, with ignition switch (v) PA models up to RA647649	1
13	PRC3408	SWITCH ASSEMBLY, ignition Up to (v) MA610293	1
	STC932	SWITCH ASSEMBLY, ignition From (v) NA610294 to RA647649	1
	STC1436G	SWITCH ASSEMBLY, ignition From (v) SA647650 on	1

TECH TIP: ABS Warning Light - Troubleshooting




If your Classic has ABS brakes and your ABS warning light comes on and stays on, you may have a bad relay. The relays are located under the drivers seat behind the seat surround and under the left seat track. The center relay is usually the one that causes the false signal. The replacement valve relay is part # PRC9603 on page 50 under ABS Sensors.

IIL No.	Part No.	Description	Qty. Rqd.
---------	----------	-------------	-----------




14	DRC2481G	SWITCH, door mirror adjusting, 6 pin connection Non-memory models	1
15	PRC5072	SWITCH, indicator, hazard, dip, horn	1
16	RTC3635	BULB, hazard warning light switch	1
17	PRC5073G	SWITCH, wash/wipe, front Up to (v) JA351032	1
	PRC8724	SWITCH, wash/wipe, front From (v) KA351033 on	1
18	PRC9956	SWITCH, wash/wipe, rear From (v) KA351033 to RA647649	1
19	PRC5425	SWITCH, head/side lamps	1




PRICES SUBJECT TO CHANGE.
Call for the Latest Pricing and Availability.

Ill. No.	Part No.	Description	Qty. Rqd.
20	ATU1027LG	SWITCH, auxiliary, lights <i>Up to (v) RA647649</i>	1
21	PRC6797G	SWITCH, auxiliary, heated front windshield <i>Up to (v) RA647649</i>	1
22	RTCS604G	BULB, green, auxiliary switch <i>Up to (v) RA647649</i>	A/
	RTCS759G	BULB, red, auxiliary switch <i>Up to (v) RA647649</i>	A/R
	RTCS605G	BULB, amber, auxiliary switch <i>Up to (v) RA647649</i>	A/R
23	ADU4903LG	BULB HOLDER, heater controls	*NLA
24	RTC3635	BULB, heater controls	4
25	PRCS797G	SWITCH, cruise control, set/accelerator <i>Up to (v) RA647649</i>	1
26	PRC6590G	SWITCH, cruise control, reset/cancel <i>Up to (v) RA647649</i>	1
	AMR3361G	SWITCH, cruise control, reset/cancel <i>From (v) SA647650 on</i>	1
27	PRCS254	SWITCH, RH window lift, console <i>Up to (v) NA models</i>	2
	PRCS255	SWITCH, LH window lift, console <i>Up to (v) NA models</i>	2
	PRCS255	SWITCH, window lift, console <i>From (v) PA models to RA647649</i>	4
28	AMR2496	SWITCH, window lift, console <i>From (v) SA647650 on</i>	4
29	PRC3912	SWITCH, window lift, rear door <i>Up to (v) LA464553</i>	2
	PRCS254	SWITCH, window lift, RH rear door <i>From (v) MA464554 on</i>	1
	PRCS255	SWITCH, window lift, LH rear door <i>From (v) MA464554 on</i>	1
30	PRCS255	SWITCH, sunroof, roof console	1



Ill. No.	Part No.	Description	Qty. Rqd.
----------	----------	-------------	-----------




31	PRC8095	SWITCH, seat, RH Non-memory seats only	1
	PRC8096	SWITCH, seat, LH Non-memory seats only	1
	PRC7153K	SWITCH, seat, LH Memory seats only	1
32	PRC6030G	SWITCH, seat squab, RH Non-memory seats only	1
	PRC6032G	SWITCH, seat cushion, RH Non-memory seats only	1
	PRC6029G	SWITCH, seat squab, LH Memory and non-memory seats	1
	PRC6031G	SWITCH, seat cushion, LH Memory and non-memory seats	1

*NLA = No Longer Available

Ill. No.	Part No.	Description	Qty. Rqd.
----------	----------	-------------	-----------

33	MWC6165LCSG	TOP PANEL, seat switch housing, LH, Grey <i>Up to (v) JA351032</i>	1
	MWC6166LCSG	TOP PANEL, seat switch housing, RH, Grey <i>Up to (v) JA351032</i>	1
	MWC6165RUNG	TOP PANEL, seat switch housing, LH, Bokhara <i>From (v) KA351033 to MA472326</i>	1
	BTR1333RUNG	TOP PANEL, seat switch housing, LH, Bokhara <i>From (v) MA472327 to RA647649</i>	1
	BTR1334RUNG	TOP PANEL, seat switch housing, RH, Bokhara <i>From (v) MA472327 to RA647649</i>	1
34	MWC6170LCSG	HOUSING, seat switch, RH, Grey <i>Up to (v) JA351032</i>	1
	BTR1336RUNG	HOUSING, seat switch, RH, Bokhara <i>From (v) MA472327 to RA647649</i>	1
	BTR1335RUNG	HOUSING, seat switch, LH, Bokhara <i>From (v) MA472327 to RA647649</i>	1



35	BTR1955G	BEZEL, automatic transmission selector <i>From (v) NA610294 to RA647649</i>	1
36	RTC6683	ILLUMINATION UNIT, auto transmission selector <i>From (v) NA610294 to RA647649</i>	1
37	573289	BULB, automatic transmission selector display <i>Up to (v) RA647649</i>	1
38	STC4008G	ILLUMINATION UNIT, auto transmission selector <i>From (v) SA647650 on</i>	1

Instruments & Switches



TO ORDER, CALL 1-800-533-2210